Joint Sector Group for ERA Task Force on wagon/axle maintenance

Final report on EVIC sampling programme

ERA, Lille 13th December 2011





2. Results per end of November

3. Analysis NDT indication after treatment




Member	Number of axles (total)	% of total	sampling theoretical	sampling decided	Number of wheelset already checked	NDT System	COR	RID	High Ioad	Drop Ioad
PKP	280 000	17%	4 065	4 000	195		2000		1000	1000
SBB	30 000	2%	436	600	6				350	250
AAE	40 000	2%	581	750	707	UT man			50	700
SNCB	60 000	4%	871	800	853				400	400
HUPAC	16 000	1%	232	300	-				150	150
Total	426 000	0	6 185	6 450	1 761		2 000	-	1 950	2 500
DB SR D	370 000	22%	5 372	5 000	3 728		3300		500	1200
TI	115 000	7%	1 670	1 300	-	UT auto	200		1100	
ÖBB	60 000	4%	871	700	707	UT auto			400	300
AAE	80 000	5%	1 162	1 000	826				200	800
Total	625 000		9 074	8 000	5 261		3 500	-	2 200	2 300
UIP	300 000	18%	4 356	6 000	4 906			6000		
SNCF	291 000	18%	4 225	3 550	669	MT	500		1850	1200
SLO	11 000	1%	160	-						
Total	602 000		8 740	9 550	5 575		500	6 000	1 850	1 200
Total	1 653 000		24 000	24 000	12 597		6 000	6 000	6 000	6 000

unife



Wheelsets sampled per Risk Category, state per end of November 2011



30.11.2010:	2.930 in total
01.03.2011:	5.739 in total
30.08.2011:	10.623 in total
30.11.2011:	12.597 in total

•≈ 52% of the sampling volume has been checked up to now

(11/2010: 10%, 03/2011: 24%, 09/2011: 44%)







2. Results per end of November

3. Analysis NDT indication after treatment





















2. Results per end of November

3. Analysis NDT indication after treatment



3. Analysis NDT indication after treatment

EVIC	Defect in visual EVIC Zone					
EVIC categories	Yes	No				
NOK	 432422 defect 36 (deeply pitted corrosion scars on shaft) depth 1,4 mm 8827 ? 650053 length 5 mm axial on shaft 656405 length 20 mm axial on shaft 920279 length 13 mm axial on shaft 921446 length 5 mm axial on shaft 910522 length 20 mm axial on shaft 106058 surface category 4 + transverse indication depth 2mm. 0013 length 55 mm longitudinal on shaft. 148504 lenght 100 mm longitudinal on shaft 	86676 defect 31 (sharp edged circumferential fluting) on abutment both side 82000021005 ? 525592 lenght 4mm quer				
С	543364surface category 3 on shaft784888lenght 20 mm transverse on shaft168478?	035004 lenght 65 mm longitudinal on shaft				
OK		1				





2. Results per end of November

3. Analysis NDT indication after treatment



4. Conclusions

Statistical treatment of axles sampled

	NDT Not Ok After treatment	NDT Ok After treatment	Ratio	95% Confidence range	99% Confidence range
EVIC Ok	0	5664	0 ‰	0 – 0.68 ‰	0 – 1.17 ‰
EVIC C	3	4258	0.7 ‰	0.24 – 2.07 ‰	0.18 – 2.78 ‰
EVIC Ok or C	3	9922	0.3 ‰	0.1 – 0.89 ‰ 🔇	0.08 – 1.2 %
EVIC Not Ok	14	2480	5.6 ‰	3.36 – 9.45 ‰	2.87 – 11.05%
Total	17	12402	1.37 ‰	0.86 – 2.19 ‰	0.74 - 2.53 ‰

Estimators:

Relative number of NDT not ok – axles in EVIC not ok – sample higher than in EVIC ok sample by a factor of 19

Confidence-intervals:

- 99 % Confidence-intervals for ratios of NDT not ok to EVIC ok/EVIC C and EVIC not ok do not overlap
- ➔ Positive effect of EVIC is significant to a level of 99 %



4. Conclusions

NDT results vs. risk categories – November 2011

	Corrosive traffic	Dangerous goods	Drop loading	High loading	Normal operation		
NDT not Ok	0	27	19	4	16	Before treatment	
NDT Ok	1026	4892	2987	1421	2022		
NDT not Ok	0	8	2	2	5	After treatment (axle scrapped)	
NDT Ok	1026	4656	2981	1373	2029		

Conclusions:

- NDT not Ok lower than 1%, no significant differences between risk domains
- No need for special attention to a particular risk domain



- All the C and OK EVIC axle comes from normal maintenance flow.
- All the EVIC OK axle NDT before treatment NOK are NDT OK after treatment.
- For C EVIC axle only (4/11) 36 % of NDT NOK are in the EVIC zone and 75% (3/4) are NDT OK after treatment. One cannot be repaired due to too small diameter (surface cat 4).
- For NOK EVIC axle 90% (27/30) of NDT NOK are in the EVIC zone and
 - ✓ 59% (16/27) of them are NDT OK after treatment;
 - ✓ 41% (11/27) are NDT NOK after treatment ;
- The normal maintenance rules allow to scrap 550 wheelset.



Sampling can be stopped!

